
PORTWEST.

SIZE CHART

STYLE CA110

A110 DESCRI

X Back Contrast Tape S/S T-Shirt



Measurements Are For A Fully Relaxed Fabric, In Cm's		xs	s	М	L	XL	XXL	3XL	4XL	5XL	Tolerance (+)
А	Chest	92	100	108	116	124	136	144	152	164	1
В	Back Length (include collar)	70	74	75	76	77	78	79	80	81	1
С	Hem Circumference	92	100	108	116	124	136	144	152	164	1



© COPYRIGHT AND PROTECTED: **PORTWEST**WESTPORT BUSINESS AND TECHNOLOGY PARK, WESTPORT, CO MAYO, IRELAND

DISCLAIMER

These charts are recommendations only. Fit may vary depending on comfort level of the consumer and whether or not product is being worn over different layers of clothing. For best results, measure over your undergarments and use a flexible measuring tape.